

Vector



zoom in detail



Bitmap





zoom in detail



Color Mode / Spot Color



Pantone 110 U



General Print File Setup

Back Side Finish Look



Front Side Finish Look



Final Finishing Product



Offset Printing  K:100%



Offset Printing



Matte Gold Foil Stamp




Spot UV




Die Cut Sizes

Rounded Corners Die Cut




6mm radius die cut rounded corners




3mm radius die cut rounded corners

Frost PVC Die Cut



Metal Custom Die Cut Shape



Die Cut Setup Example


Back Side Finish Look




Matte Gold Foil Stamp



3mm radius die cut rounded corners



Metal Card Print File Setup



Final Finishing Product



PROCESS



PANTONE Black C
* for reference only



Cut Through



Laser Engraving



Black Metal

When indicates cut through, etching, and laser engrave, please use a bright colour to clearly indicate which is which

When using a spot colour, please indicate in a PMS Solid C for reference only on the side of the finished look

Correct Print File Format

Vector based graphics
such as ai, eps




Incorrect Print File Format

Bitmap based graphics
such as : jpg, bmp, png, psd, tiff



Laser Engraving Quick Business Card Print File Setup

For laser engraving quick business cards, please use RGB color mode.



Final Finishing Product



The area that you want to laser cut such as card size, shape, or cut through It has to be stroke in RED (255, 0, 0) in 0.0001 pt line thickness.



The area that you want to etch, make sure the elements are in solid BLACK (0,0,0)

